

SERVICE LETTER

DATE: 23 JULY 2010

PAGE 1 OF 2

AIR-CONDITIONING SYSTEM MAINTENANCE

MODELS AFFECTED: All MD900 helicopters.

This Service Letter is issued to make sure owners and operators correctly maintain the air-conditioning system. There has been a wide range of “times between failure” for refrigerant compressor assembly 900P3250303-105.

To make sure the air-conditioning system is correctly maintained and to keep the designed level of reliability, operators must follow the instructions for the maintenance, removal/replacement, and servicing of the compressor assembly.

CAUTION Failure to follow the instructions in Rotorcraft Maintenance Manual CSP-900RMM-2 (ref. Section 12-00-00 and Section 21-50-00) can have an effect on the warranty.

- (1). Make sure the personnel that maintain and service the air-conditioning system have the necessary education and experience. The air-conditioning system has complex and specialized components that require specific knowledge.
- (2). The receiver dehydrator must be replaced each time the air-conditioning system is opened.
- (3). When the air-conditioning system is charged or evacuated, use the refrigerant recovery and recycling station (T701) (ref. Section 12-00-00, Air-Conditioning System Charging/Evacuation).
- (4). Measure the refrigerant oil quantity removed during evacuation.
- (5). Use only approved refrigerant oil (ref. CSP-SPM) in the air-conditioning system:
 - (a). Use Daphne Hermetic Oil 150CX [daphne hermetic oil (C116)] for R12 refrigerant systems.
 - (b). Use RG20, RS20, or Daphne Hermetic Oil PR [daphne hermetic oil (C117)] for R-134A refrigerant systems.

CAUTION Do not over-service the air-conditioning system with R12 refrigerant (C806) or R-134A refrigerant (C815). MDHI recommends the air-conditioning system be serviced with **0.5 lb (0.23 kg)** less than recommended by the RMM of R12 refrigerant (C806) or R-134A refrigerant (C815) for the first maintenance operational check.

- (6). Follow the instructions in CSP-900RMM-2 (ref. Section 12-00-00 and Section 21-50-00).
- (7). There is a window at the top of the receiver dehydrator and on later systems a sight glass in the refrigerant line near the servicing parts, that is used to make sure the air-conditioning system is serviced correctly. Follow the procedures in the applicable Rotorcraft Flight Manual and CSP-900RMM-2 to start the right engine and operate the air-conditioning system.
 - (a). Monitor the window (or the tubes near the evaporator) for bubbles.
 - (b). Slowly add R12 refrigerant (C806) or R-134A refrigerant (C815) until all bubbles are removed.

DATE: 23 JULY 2010
PAGE 2 OF 2

SERVICE LETTER

- (c). Do not add more than the total quantity of R12 refrigerant (C806) or R-134A refrigerant (C815) shown in CSP-900RMM-2 for the applicable system.



Be careful when you install or remove the compressor assembly on/from the engine drive pad. Do not apply a load or allow a shock or impact on the splined drive shaft. This can damage the shear pin and cause an early shear pin failure.

- (8). After installation of the compressor assembly (ref. Section 21-50-00), you also must internally clean the condenser, evaporator, and all hoses and tubes; and replace the receiver dehydrator.

For further assistance, contact the Field Service Department at MDHI, Mesa, Arizona. Telephone 1-800-388-3378 or (480) 346-6387. DATAFAX: (480) 346-6813.