



HN-207
DN-144
EN-32
FN-21

SERVICE BULLETIN

DATE: 22 FEBRUARY 2000
PAGE 1 OF 1

SERVICE BULLETIN / SERVICE INFORMATION NOTICE CANCELLATION

SUBJECT: SHIMMING OF ELASTOMERIC TAIL ROTOR BEARINGS

This Service Bulletin / Service Information Notice, dated 11 July 1986, has been cancelled in its entirety.

For 369H Model helicopters, refer to CSP-H-5 (Component Overhaul Manual), dated 15 July 1989, or later, for current shimming procedure.

For 369D/E/FF Model helicopters, refer to CSP-COM-5 (Component Overhaul Manual), Revision 10, or later, for current shimming procedure.