



HN-226.1  
DN-172.1  
EN-63.1  
FN-51.1

# SERVICE BULLETIN

DATE: 4 SEPTEMBER 1990  
PAGE 1 OF 3

**/// MANDATORY ////////////////////////////////////// MANDATORY ////////////////////////////////////// MANDATORY ///**

**SUBJECT:** ONE-TIME INSTALLATION OF 369D24054-3 WARNING DECALS IN THE ENGINE COMPARTMENT AREA

**SUMMARY:** Proper and safe maintenance in the engine bay area is critical. The applicable maintenance manuals should be used at all times.

## WARNING

Failure to properly install, align and torque fuel, oil and air tubes/lines and fittings could result in engine damage/failure.

**PURPOSE:** The purpose of this Notice is to install 369D24054-3 warning decals in the engine compartment which will help alert maintenance personnel of the importance to properly reinstall any fuel, oil or air tubes that have been removed or disconnected.

**MODELS AFFECTED:** All MD Helicopters, Inc. (MDHI) 369, including the 369A (OH-6A) Series helicopters not equipped with 369D24054-3 warning decals.

**TIME OF COMPLIANCE:** The requirements of this Notice shall be accomplished within the next 100 hours of helicopter operation after receipt of parts or no later than June 30, 1991, whichever occurs first. Order parts immediately after receipt of this Notice.

**ASSEMBLY/COMPONENTS TO BE INSPECTED AND CORRECTED:** 369D24054-3 engine bay area warning decals.

**REFERENCE PUBLICATIONS:** (Use the manuals listed below or any later revisions.)  
369H Basic HMI (CSP-H-2) Revised 15 January 1989  
369D/E HMI Vol. I (CSP-D-2) Revised 01 August 1989  
369F/FF HMI Vol. I (CSP-F-2) Revised 01 June 1989

**SUPPLY/PARTS:**

### PARTS LIST

<u>Nomenclature</u>	<u>Part No.</u>	<u>Qty.</u>	<u>Source</u>
Decal, warning	369D24054-3	A/R	,MDHI

**SPECIAL TOOLS/JIGS AND FIXTURES REQUIRED. N/A.**

**/// MANDATORY ////////////////////////////////////// MANDATORY ////////////////////////////////////// MANDATORY ///**



# SERVICE BULLETIN

/// MANDATORY ///  
/// MANDATORY ///  
/// MANDATORY ///

## AIRCRAFT INSPECTION AND CORRECTION PROCEDURES:

- a. Gain access to inside of the engine compartment.
- b. Verify that 369D24054-3 warning decals are installed as shown in Figure 1. If warning decals are installed, no further action is required.
- c. Ensure surface where decals are going to be installed is clean and free of oil prior to installation. Install warning decals at locations shown in Figure 1.
- d. Secure engine access door.

**WEIGHT AND BALANCE:** N/A.

## RECORDING AND COMPLIANCE:

Record compliance to this Service Information Notice in the Compliance Record section of the helicopter Log Book.

## POINTS OF CONTACT:

For further information contact your local MDHI Field Service Representative (refer to the latest revision of the Product Support handbook for address and telephone numbers) or contact the Field Service Department, at MDHI, Mesa, Arizona. Telephone: 1-800-445-1516 or (602) 891-6342.

The resultant alteration to affected models as prescribed by procedures in this Notice has been shown to comply with Federal Aviation Regulations and is FAA Approved.

/// MANDATORY ///  
/// MANDATORY ///  
/// MANDATORY ///

# SERVICE BULLETIN

DATE: 4 SEPTEMBER 1990  
PAGE 3 OF 3

MANDATORY MANDATORY MANDATORY




Figure 1. Engine Compartment Warning Decal Installation.

MANDATORY MANDATORY MANDATORY