



TB369H-001R1\* TB369D-001R1\*  
TB369E-001R1\* TB369F-001R1\*  
TB500N-001R1\* TB600N-001R1\*

# TECHNICAL BULLETIN

DATE: 15 MARCH 2002  
PAGE 1 OF 1

\* Supersedes TB369H-001, TB369D-001, TB369E-001, TB369F-001, TB500N-001, TB600N-001, dated 28 April 1998.

## DOOR SEAL REPLACEMENT

This Technical Bulletin has been incorporated into the maintenance manual and is cancelled in its entirety.

For 369H Model helicopters, refer to CSP-H-2 (Basic Handbook of Maintenance Instructions), dated 15 May 2001 or later for the current door seal replacement procedure.

For 369D/E/FF, 500N and 600N Model helicopters, refer to CSP-HMI-2 (Basic Handbook of Maintenance Instructions), dated 5 November 2001 or later for the current door seal replacement procedure.

Remove this Technical Bulletin from your files one year after the issue date.