



# SERVICE LETTER

DATE: 27 OCTOBER 2009

PAGE 1 OF 2

## MAIN ROTOR DRIVE PLATE O-RING PACKING

**MODELS AFFECTED:** MD900 helicopter serial numbers 900-00008 thru 900-000143.

This Service Letter is issued to tell owners and operators that a new PN 900R2101129-101 O-ring packing is to be installed with the main rotor drive plate. Installation of the O-ring packing will help prevent moisture between the faying surfaces of the main rotor upper hub and drive plate, which can cause corrosion.

Install PN 900R2101129-101 O-ring packing the next time the main rotor drive plate is removed for maintenance (ref. CSP-900RMM-2, 63-10-00, Drive Shafts/Clutches/Couplings, Removal/Installation).

For further assistance, contact the Field Service Department at MDHI, Mesa, Arizona. Telephone 1-800-388-3378 or (480) 346-6387. DATAFAX: (480) 346-6813.

DATE: 27 OCTOBER 2009  
PAGE 2 OF 2

# SERVICE LETTER

**This page intentionally left blank!**