

# SERVICE LETTER

DATE: 26 JANUARY 2010  
PAGE 1 OF 1

## BENDIX/KING BY HONEYWELL – WINGMAN SERVICES: DATABASE DOWNLOADS AND EGPWS UPDATES

**MODELS AFFECTED:** All MD900 helicopters that utilize any of the following databases –  
Reference: Databases for KLN 35A/KLN 88/KLN

**MODELS AFFECTED:** 89/KLN 89B/KLN 90/KLN 90A/KLN90B/KLN 94/KLX 100/KLX  
135/KLX 135A/KLN 900.

Honeywell has issued an URGENT SAFETY BULLETIN dated 11 January 2010.

Honeywell was informed by their data supplier, Jeppesen, that the data file delivered to Honeywell contained incorrect Dynamic Magnetic Variations for all terminal and enroute waypoint records. For that reason, it is imperative that the incorrect databases NOT be used for arrival, departure, or approach operations.

The Honeywell Bulletin states; “To fix this issue, a corrected database must be installed prior to the next flight.”

Detailed information regarding this Urgent Safety Bulletin and corrective actions can be found on the Bendix/King web site at:

[https://www.bendixking.com/wingman/servlet/com.honeywell.brga.wingman.gps.GpsUserRoles?page=database\\_downloads](https://www.bendixking.com/wingman/servlet/com.honeywell.brga.wingman.gps.GpsUserRoles?page=database_downloads)