



HL-104  
DL-79

# SERVICE LETTER

DATE: 18 MAY 1988  
PAGE 1 OF 1

TO: All Owners and Operators of McDonnell Douglas Helicopter Company (MDHC) 369H Series helicopters, including the 369A (OH-6A) Series helicopter, and 369D Series helicopters that have passenger/cargo hoists installed.

## **ADDITIONAL INSPECTION REQUIREMENTS OF THE BREEZE-EASTERN RESCUE HOIST SYSTEM**

Breeze-Eastern, a division of TransTechnology Corporation, has issued a Customer Advisory Bulletin (CAB-100-30) which outlines a procedure to significantly improve the reliability of the rescue hoist system and, more importantly, further limit the possibility of personnel safety hazard.

Owners and operators can obtain copies of the Bulletin referenced below at 700 Liberty Avenue, Union, New Jersey, 07083.

TELEPHONE: (201) 686-4000

TELEX (TWX): 138212

### REFERENCE

CAB-100-30, Customer Advisory Bulletin, Breeze-Eastern Corp.