



SERVICE LETTER

HL-119
DL-94
EL-45
FL-38

DATE: 15 DECEMBER 1989
PAGE 1 OF 1

TO: ALL OWNERS AND OPERATORS OF MCDONNELL DOUGLAS HELICOPTER COMPANY (MDHC) 369 SERIES HELICOPTERS EQUIPPED WITH CARGO HOOK INSTALLATIONS.

COMPLIANCE TO BREEZE-EASTERN CUSTOMER SERVICE BULLETIN CSB-120 (WARNING PLATE FOR CARGO HOOKS)

Breeze-Eastern, a division of TransTechnology Corporation, has informed MDHC that they have issued a Customer Service Bulletin requiring Breeze-Eastern cargo hook operators to affix a warning plate to those affected cargo hooks. Instructions as to where and how to affix the warning plate (Breeze-Eastern Part No. 13830-1) are included in CSB-120, dated 01 May 1989. Breeze-Eastern request operators to provide them with the Part No. and Serial No. of their cargo hook and they will send a copy of the CSB and a warning plate directly to the operator. Breeze-Eastern is providing the warning plate to cargo hook operators free of charge.

Send cargo hook Part No. and Serial No. along with operators name and address to:

Breeze-Eastern
700 Liberty Avenue
Union, New Jersey 07083

Phone: (201)686-4000
Datafax (201)686-9292

A handwritten signature in black ink that reads 'Cary Brown'.

Cary Brown, Manager,
Product Support Department
McDonnell Douglas
Helicopter Company