



SERVICE LETTER

HL-127.2*

DL-103.2*

EL-54.2*

FL-48.2*

NL-001.2*

DATE: 10 NOVEMBER 2000

PAGE 1 OF 1

* Supersedes Service Letters HL-127.1, DL-103.1, EL-54.1, FL-48.1 and NL-001.1, dated 15 March 1995.

TO: ALL OWNERS AND OPERATORS OF MD HELICOPTERS (MDHI) 369 AND 500N SERIES HELICOPTERS.

INTRODUCTION OF THE USE OF AN ALTERNATE DRIVE SYSTEM LUBRICANT

This Service Letter is cancelled in its entirety.

The information contained in this Service Letter is incorporated into the Basic Handbook of Maintenance Instructions and the Rotorcraft Flight Manuals.

This Service Letter is valid for one year from the date of issue and can be discarded at that time.