



# SERVICE LETTER

DATE: 06 MAY 2010

PAGE 1 OF 2

## YEARLY FUEL TRANSFER SYSTEM FUNCTIONAL CHECK

**MODELS AFFECTED:** All MD600N helicopters without the airframe fuel filter option.

This service letter is issued to tell owners and operators of the yearly requirement to do a fuel transfer system functional check. The fuel transfer system functional check was added to Table 1, Yearly Inspection (CSP-HMI-2, Section 05-20-15). The fuel transfer system functional check procedure is located in section 28-00-60 of the CSP-HMI-2 maintenance manual.

MDHI currently has the Fuel Transfer System Functional Tester (ST803) available to rent.

For further assistance, contact the Field Service Department at MDHI, Mesa Arizona. Telephone 1-800-388-3378 or (480) 346-6387. DATAFAX: (480) 346-6813.

DATE: 06 MAY 2010  
PAGE 2 OF 2

# SERVICE LETTER

**This page intentionally left blank!**