



SL369H-135  
SL369E-066  
SL500N-011

SL369D-114  
SL369F-059  
SL600N-008

# SERVICE LETTER

DATE: 23 MAY 2000  
PAGE 1 OF 1

\* Supersedes and cancels Service Information Letters HL-71.12, DL-30.12, EL-8.6 and FL-25.4, dated 07 April 1995.

## AVAILABILITY OF FEDERAL AVIATION ADMINISTRATION AIRWORTHINESS DIRECTIVES AFFECTING MD HELICOPTERS

**TO:** ALL OWNERS AND OPERATORS OF MD HELICOPTERS.

Federal Aviation Administration Airworthiness Directives affecting MD helicopters can be viewed and printed from the Internet at: "<http://av-info.faa.gov/>".

If Internet access is not available, owners and operators can contact the Federal Aviation Administration for information on obtaining paper or microfiche copies at the following address.

U.S. Department of Transportation  
Federal Aviation Administration  
Regulatory Support Division  
Airworthiness Program Branch, AFS-610  
P.O. Box 26460  
Oklahoma City, OK 73125-0460  
FAX 405-954-4104