

SERVICE LETTER


DATE: 08 JULY 1996

PAGE 1 OF 2

TO: ALL OWNERS AND OPERATORS OF MCDONNELL DOUGLAS HELICOPTER SYSTEMS (MDHS) MD900 SERIES HELICOPTERS.

SUBJECT: TRANSMISSION ACCESS DOORS AND BATTERY DOOR FASTENER UPGRADE. (REF. CR #110679)

MDHS is now offering upgraded locking hardware for the main transmission access doors and the battery access door. The improved locking hardware allows the operator to open those access doors without the use of any tools.



9L06-011

All slotted recess Camloc® fasteners used on the transmission access doors and battery access door may be replaced with the following folding bail handle type fasteners:

PARTS/SUPPLIES – BATTERY ACCESS DOOR			
Nomenclature	Part No.	Qty.	Source
Stud, Folding Bail Handle	26S22-4B or (HS4431-4G)	2	Camloc® or (MDHS)
Retaining Ring, Solid	2600-LW or (HS4432-2)	2	Camloc® or (MDHS)

PARTS/SUPPLIES – TRANSMISSION ACCESS DOORS			
Nomenclature	Part No.	Qty.	Source
Stud, Folding Bail Handle	40S47-5A or (HS4436F5N)	20	Camloc® or (MDHS)
Grommet, 1/4 Turn Fastener *	4002-NS or (HS4434-4C)	20	Camloc® or (MDHS)
Snap Ring, Retaining *	40G26-1 or (HS4424-1C)	20	Camloc® or (MDHS)

* **NOTE:** Original grommets and snap rings need not be replaced unless damaged.



DATE: 08 JULY 1996
PAGE 2 OF 2

SERVICE LETTER

John Reagan, Dept. Manager,
Commercial Customer Support
McDonnell Douglas
Helicopter Systems

POINTS OF CONTACT: For further assistance, contact your local MDHS Field Service Representative (refer to the latest revision of the Business Development and Customer Support handbook for address and telephone numbers) or contact the Field Service Department at MDHS, Mesa Arizona. Telephone: 1-800-388-3378 or (602) 891-6342. DATAFAX: (602) 891-6782.