



SL900-036R1

# SERVICE LETTER

DATE: 10 MARCH 2000

PAGE 1 OF 1

\* Supersedes SL900-036, dated 09 October 1997. Reason for Revision: To remove reference to Pratt & Whitney Canada Service Bulletin 28122 (Cancelled) and add reference to Pratt & Whitney Canada Service Bulletin 28111.

## **ELECTRONIC ENGINE CONTROL (EEC) P&WC S.B. 28111**

**MODELS AFFECTED:** All MD900 Series Helicopters, serial numbers 00002 thru 00051.

Pratt & Whitney Canada (P&WC) Service Bulletin 28122 is cancelled and superseded by P&WC Service Bulletin 28111, which requires that the 3116655-12 EEC replace all previous configurations. MD900 operators should review P&WC Service Bulletin 28111 for compliance requirements.

**NOTE:** 3116655-12 EEC is one-way interchangeable with all prior EEC configurations.

**POINTS OF CONTACT:** For further assistance, contact your local MDHI Field Service Representative (refer to the latest revision of the "At Your Service" handbook for address and telephone numbers) or contact the Field Service Department at MDHI, Mesa, Arizona. Telephone 1-800-388-3378 or (480) 346-6387. DATAFAX: (480) 346-6813.