



SERVICE LETTER

DATE: 20 JUNE 2008

PAGE 1 OF 2

* Supersedes Service Letter SL900-060, dated 31 March 2008. Revised to correct oil hose nomenclature.

BETTER TRANSMISSION OIL HOSES

MODELS AFFECTED: MD900 helicopters serial numbers 900-00008 thru 900-00124.

New 900D3409527-101 left oil in hose, 900D3409527-104 right oil in hose, and 900D3409528-101 oil out hose are now available from MD Helicopters, Inc. The new hoses will give better service life. Helicopter serial numbers 900-00119 and subsequent have the new oil out hoses installed. Helicopter serial numbers 900-00125 and subsequent have both the new oil out and oil in hoses installed. Helicopters serial number 900-00008 thru 900-00018 that do not have 900D3658501-103 heat exchangers installed, must install 900D3658501-103 heat exchangers before installation of the new oil in hoses. Contact MDHI Parts Sales Department to order new hoses.

For further assistance, contact the Field Service Department at MDHI, Mesa, Arizona. Telephone 1-800-388-3378 or (480) 346-6387. DATAFAX: (480) 346-6813.



DATE: 20 JUNE 2008
PAGE 2 OF 2

SERVICE LETTER

This page intentionally left blank!