

**HUGHES
SERVICE INFORMATION
LETTER**

LETTER NO. HL-38

DATE 5/5/75

PAGE 1 OF 1

TO—All owners and operators of Hughes Helicopters

SUBJECT: MODIFICATION KIT AVAILABILITY - TORQUEMETER
BLEED VALVE PART NO. M50043 AND STATIC
PRESSURE TUBE BLEED VALVE PART NO. M50439

MODELS AFFECTED: 369HE 0101E THROUGH 0215E
369HM 0101M THROUGH 0269M
369HS 0101S THROUGH 0700S

This Service Information Letter is to advise owners and operators of the availability of the subject modification kits.

The bleeding of the lines of all entrapped air in some instances can be a time consuming and inconvenient task.

Installation of the Drain Valves can eliminate many of the problems associated with instrument bleeding.

The kits may be procured by placing an order with your Service Center, Sales Company or Distributor.



Edward Koch, Manager
Customer Service Department
Hughes Helicopters

Customer Service Department - Hughes Helicopters - Culver City, California