



SERVICE LETTER

HL-118.1*
DL-93.1*
EL-44.1*
FL-37.1*

DATE: 27 SEPTEMBER 1991
PAGE 1 OF 1

*Supercedes Service Information Letters HL-118, DL-93, EL-44 and FL-37, dated 12 December 1989.

(I) Denotes portion of text added or revised.

TO: All owners and operators of McDonnell Douglas Helicopter Company (MDHC) 369 Series helicopters.

AVAILABILITY OF AUTRONICS CORPORATION ELECTRICAL COMPONENT EXCHANGE PROGRAM

Autronics Corporation in Arcadia, California, is now offering a factory exchange program involving dimmer controls and engine power out (EPO) units.

Autronics charges \$960.00 (U.S. Funds) for a factory exchange unit on any of the 369H6425 series dimmer controls and 369A4514 series EPO units. The 369A4540-3 EPO unit is no longer available from Autronics or MDHC. The 369A4540-3 EPO unit was used on early configuration 369H series helicopters equipped with C-18 engines.

Autronics is located at:

Autronics Corporation
3 14 E. Live Oak Drive
Arcadia, CA. 91006-5695
Phone: (818)445-5470

John Reagan, Manager,
MD500 Customer Support Dept.
McDonnell Douglas
Helicopter Company