



SERVICE LETTER

DATE: 26 JUNE 1997

PAGE 1 OF 1

VENT SYSTEM AIR DUCT / ADDITIONAL AIR OUTLETS INSTALLATION

MODELS AFFECTED: ALL McDonnell Douglas Helicopter Systems (MDHS) MD900 Series Helicopters, serial numbers 00010 thru 00038.

MDHS has assembled two kits (Vent System Air Duct Installation, P/N 900P5250305 and Additional Air Outlets Installation, P/N 900P5250308) which, when installed, will improve environmental conditions inside the helicopter during operation. These kits will increase output flow and provide additional air outlets in the vent and air conditioning system.

Contact MDHS Warranty and Repair Department to procure the kits listed above. Refer to Modification Instructions for Vent System Air Duct / Additional Air Outlets Installation, MOD MD9009500003 for installation instructions of the two kits.

POINTS OF CONTACT: For further assistance, contact your local MDHS Field Service Representative (refer to the Business Development and Customer Support handbook for address and telephone numbers) or contact the Field Service Department at MDHS, Mesa, Arizona. Telephone: 1-800-388-3378 or (602) 891-6342. DATAFAX: (602)891-6782.